



DMD/342/2015

4th November, 2015

Boris Bastic
Executive Director
Enikon (T) Ltd
P. O. Box 4703
Dar es Salaam

RE: TANK S5&S6 REFURBISHMENT PROJECT HSSEQ PERFORMANCE

Dear Sir,

Enikon (T) Ltd acted as EPC-contractor for TIPER – Tanzania International Petroleum Reserves Ltd in Dar es Salaam (National Oil Company of Tanzania), revamping 2 (two) existing tanks S-5 & S-6 for storage of hydrocarbons.

Tank diameter: 54,87m

Tank height: 16,5m

Enikon have executed repair & adjustment works on the tanks to be equipped with Aluminium Dome Roofs all in accordance with API 650.

Main tasks:

- Tank bottom plates replaced.
- Both tank lifted by using jacking system (in total 420 T was lifted with on lift per tank)
- Annular plates replaced.
- Concrete foundation repaired.
- Wind girder replaced.
- Partly shell plates replaced.
- Aluminium Dome roof installation.
- Additional tank upper shell stiffeners installed with additional secondary wind girder.
- Sandblasted and painted internally and externally.
- Installation of new fire fighting system.
- Installation of new process piping (14")
- Installation main manifold (14")

TANZANIA INTERNATIONAL
PETROLEUM RESERVES LTD.
P. O. Box 2608, DAR-ES-SALAAM
TEL: +255 22 511500, FAX: 2820183

During two years the entire project safety conduct of Enikon was on the highest level with respect to TIPER HSSEQ policies and procedures.

Safety Record:

No. of accidents with loss time injury

No. of working days at TIPER

No. of working days without accident

Total No. of injuries occurred per million hours (T.R.I.R)

Your Sincerely,



Paulo Mnzava
Deputy Managing Director

TANZANIA INTERNATIONAL
PETROLEUM RESERVES LTD.
P. O. Box 2608, DAR-ES-SALAAM
TEL: +255 22 511500, FAX: 2820183